

Message

From: Chin, Lucita [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=EA404E3F56574242AEE0811A07E309FC-CHIN, LUCITA]
Sent: 12/12/2014 9:06:04 PM
To: Shea, Valois [Shea.Valois@epa.gov]; Minter, Douglas [Minter.Douglas@epa.gov]
Subject: RE: Well rehabilitation record

We can talk more about this next week.

Ex. 5 Attorney Client (AC)

Lucita

Lucita Chin
Associate Regional Counsel
U.S. EPA Region 8
1595 Wynkoop St.
Denver, CO 80202
303.312.7832

From: Shea, Valois
Sent: Friday, December 12, 2014 2:02 PM
To: Minter, Douglas; Chin, Lucita
Subject: FW: Well rehabilitation record

This form takes care of 2 out of 3 items:

- 1) Documentation that the piping between the well and the residence has been disconnected.
- 2) Classifying the well use as "stock" through the DENR Water Rights Program.

The 3rd item is to document the source of drinking water for the residence. They proposed that a cistern will be installed and Powertech will haul water to fill the cistern.

Ex. 5 Attorney Client (AC)

Thanks!

Valois

Valois Shea
U.S. EPA Region 8
MailCode: 8P-W-UIC
1595 Wynkoop Street
Denver, CO 80202-1129
Phone: (303) 312-6276
Fax: (303) 312-6741
Email: shea.valois@epa.gov

From: Minter, Douglas
Sent: Friday, December 12, 2014 11:48 AM

To: Shea, Valois

Subject: FW: Well rehabilitation record

Let me know if this is consistent with what John committed to. Also, please include all documentation in our files

From: John Mays [<mailto:jmays@powertechuranium.com>]

Sent: Friday, December 12, 2014 9:42 AM

To: Ken.Buhler@state.sd.us

Cc: Shea, Valois; Jack Fritz; Lisa Scheinost; Minter, Douglas

Subject: Well rehabilitation record

Ken,


Attached is a well rehabilitation form for a domestic well (#16) that Powertech and a landowner within the Dewey-Burdock Project boundary have disconnected from a seasonal residence. The well is now available for stock-use only. It is located in Fall River County, NW1/4 SE1/4 Section 1 T7S R1E. I would appreciate DENR's records being updated accordingly.

Please note that no work to the well casing was done. This was just modification to piping between the well and the residence and as such no grouting was required.

Please do not hesitate to contact me if you have any questions.

Thank you for your assistance.

Sincerely,
John



POWERTECH (USA) INC.

John M. Mays

Chief Operating Officer

Powertech (USA) Inc.

5575 DTC Parkway, Suite 140

Greenwood Village, Colorado, USA 80111-3012

(303) 790-7528 x106

(303) 242-4054 Cell

(303) 790-3885 FAX

jmays@powertechuranium.com

www.azargauranium.com